

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

A	BW Region	M + SW	PRN	180
	Waterway	M + BC	OS Sheet	
	BW Struc No	BR No 74	NGR	
	Side	TOW OFF <input checked="" type="radio"/> CEN OTH	Photo Neg No	13/4+5
	BW Owned	Y <input checked="" type="radio"/> N	MMS/PMS	
B	County	Gwent	Alt Address	
	LA District	Monmouth Torfaen		
	Parish			
	Address	BR No 74, SARON'S BRIDGE		
C	Date Listed		SAM No	
	Grade	I II* II	Protected Area	<input checked="" type="radio"/> NP AONB CA SSSI
	Serial No		Structures in Item	
D	Design Integ	A <input checked="" type="radio"/> B C D	Context	VIL - URB <input checked="" type="radio"/> ISO GRO
	Setting	A <input checked="" type="radio"/> B C D	Condition	A <input checked="" type="radio"/> B C D
	Group Value	Y <input checked="" type="radio"/> N	Present Use	ROAD BRIDGE
	Listable	Y <input checked="" type="radio"/> N		
E	Building Type	PUBLIC ROAD BRIDGE		
	Date	1) 1812 2) 3) C20 REBUILDING		
	Designer(s)	WILLIAM CROSSLEY		
	Materials	BR <input checked="" type="radio"/> ST EBR CO IR ME WD		
		TI SL CTI CER AS OTH		
	S Features/ Tech Merit			
	Date Inspected	18 10 95		

F Site Notes/List or Scheduling Description

Public road bridge. c1812 with C20 rebuilding. William Crossley engineer. Coursed rubble sandstone, heavily jointed with mortar. Northern elevation has been completely rebuilt. Elliptical arch with dressed stone voussoirs and prominent keystones. Parapet has sloping wingwalls down to terminating piers, with rubble stone copings.

G Defects

Repairs



ME180 13/04



MB180 13/05