

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

A BW Region M+SW PRN 191

Waterway M+BL OS Sheet

BW Struc No BR NO. 66 NGR

Side TOW OFF ☒ CEN ☐ OTH Photo Neg No 13/26-28

BW Owned ☒ Y ☒ N MMS/PMS

B County GWENT Alt Address

LA District Monmouth Torfaen

Parish

Address ~~CROES Y PANT BR~~, NO. 66 BROOK FARM BRIDGE

C Date Listed SAM No

Grade	I	II*	II	Protected Area	<input checked="" type="radio"/> NP	AONB	CA	SSSI
Serial No				Structures in Item				

D Design Integ A ☒ B ☐ C ☐ D Context VIL URB ☒ ISO GRO

Setting A ☒ B ☐ C ☐ D Condition A ☒ B ☐ C ☐ D

Group Value Y ☒ N ☐ Present Use ~~ROAD BRIDGE~~

Listable Y ☒ N ☐ FOOTBRIDGE

E Building Type ~~PUBLIC ROAD BRIDGE~~ ACCOMMODATION BR

Date 1) 1812 2) 3) C19 + C20 RENEWAL

Designer(s) WILLIAM CROSSLEY

Materials BR ☒ ST ☐ EBR CO IR ME WD

TI SL CTI CER AS OTH

S Features/
Tech Merit

Date Inspected 18 10 95

F Site Notes/List or Scheduling Description

Accommodation bridge. c1812 with C20 rebuilding. William Crossley engineer. Coursed rubble sandstone. Elliptical arch with dressed stone voussoirs and prominent keystones. Hump-backed parapet has been rebuilt and has flat copings, mostly replaced. Slightly protruding rebuilt terminating piers. Stone slab stile on towside set in LC20 stone frame.

G Defects

Repairs



MB191 13/26



MB191

13/27

