

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

A BW Region M+SW PRN 199
Waterway M + B C OS Sheet
BW Struc No BR NO. 60 NGR
Side TOW OFF ☒ CEN OTH Photo Neg No 15/14-16
BW Owned ☒ Y U/K N MMS/PMS

B County GWENT Alt Address
LA District Monmouth - Trefaen
Parish
Address BR NO. 60, COVERA BRIDGE

C Date Listed SAM No
Grade I II* II Protected Area ☒ NP AONB CA SSSI
Serial No Structures in Item
D Design Integ A ☒ B C D Context VIL URB ☒ ISO³ GRO
Setting A ☒ B C D Condition A B ☒ C D
Group Value Y ☒ N
Listable Y ☒ N Present Use FARM TRACK / MINOR RD

E Building Type ACCOMMODATION
~~PUBLIC ROAD~~ BRIDGE

Date 1) c1812 2) 3) C19 + C20 REBUILDING

Designer(s) WILLIAM CROSSLEY

Materials BR ☒ ST EBR ☒ CO IR ☒ ME WD
TI SL CTI CER AS OTH

S Features/
Tech Merit

Date Inspected 23 10 95

F Site Notes/List or Scheduling Description

Accommodation bridge. c1812 with C20 rebuilding. William Crossley engineer. Coursed rubble sandstone. Elliptical arch, re-enforced with steel girders to soffit. Dressed stone voussoirs and prominent keystones. Hump-backed parapet has been rebuilt with narrower courses and has flat copings. Slightly protruding terminating piers, also showing signs of renewal.

G Defects

Repairs



MB199 15/14



MB199 15/15

