| | BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY MB | | | | | | | |
|---|--|-----------|-----------|----------------------------|-------|-------------|-------|--|
| A | BW Region | Mtsw | | PRN | | 203 | | |
| | Waterway | M+BC | | OS Sheet | | | | |
| | BW Struc No | BK NO. 5 | 6 | NGR | | | | |
| | Side | TOW OFF (| CEN OTH | Photo Neg No | 0 15/ | 6+7 | | |
| | BW Owned | Ý u | I/K N | MMS/PMS | | | | |
| В | County | GWENT | | Alt Address | | | | |
| | LA District | Mount | n Torfaer | | | | | |
| _ | Parish | | | | | | · | |
| | Address | BR NO. 56 | , SQVIRES | BRIDGE. | | | • | |
| С | Date Listed | | | SAM No | | | | |
| | Grade | t I | * | Protected Area | a NP | AONB CA | SSSI | |
| | Serial No | : | | Structures in Item | : | | | |
| D | Design Integ | A B | C D | Context | VIL | |) GRO | |
| | Setting | A B | С | Condition | A (| BC | D | |
| | Group Value | Y (| N | Dresent Lies | FAT | FOOTBRIDG-E | | |
| | Listable | Y (| | Present Use | | | C | |
| E | Building Type | Accomm | OVATION 1 | BRIDGE | | | | |
| | Date | 1) 01812 | 2) | 3) CIQ + CZO REBUILDING | | | | |
| | Designer(s) | | | | | | | |
| | Materials | BR ST | EBR | со | IR | ME | WD | |
| | | TI SL | СТІ | CER | AS | отн | | |
| | S Features/ Tech Merit | | | | | | | |
| | Date Inspected | 25 1 | 0 95 | | | | | |

F Site Notes/List or Scheduling Description

Accommodation bridge. c1812 with C20 rebuilding. William Crossley engineer. Coursed rubble sandstone. Elliptical arch with dressed stone voussoirs and prominent keystones. Both elevations have been rebuilt, with heavy mortar jointing. Flat copings to parapet. Slightly protruding square terminating piers.

G Defects

Repairs

. .



