

## BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB.

A	BW Region	M+SW	PRN	149
	Waterway	M+BC	OS Sheet	
	BW Struc No		NGR	
	Side	TOW <input checked="" type="radio"/> OFF <input type="radio"/> CEN <input type="radio"/> OTH	Photo Neg No	10129
	BW Owned	<input type="radio"/> Y <input type="radio"/> U/K <input checked="" type="radio"/> N	MMS/PMS	
B	County	GWENT		
	LA District	Monmouth		
	Parish			
	Address	BARN / CATTLE SHED ADJACENT BR 93 (OFFSIDE)		
C	Date Listed		SAM No	
	Grade	<input type="radio"/> I <input type="radio"/> II* <input type="radio"/> II	Protected Area	<input checked="" type="radio"/> NP <input type="radio"/> AONB <input type="radio"/> CA <input type="radio"/> SSSI
	Serial No		Structures in Item	
D	Design Integ	A <input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D	Context	VIL <input type="radio"/> URB <input type="radio"/> ISO <input checked="" type="radio"/> GRO
	Setting	A <input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D	Condition	A <input type="radio"/> B <input checked="" type="radio"/> C <input type="radio"/> D
	Group Value	Y <input checked="" type="radio"/> N <input type="radio"/>	Present Use	CATTLE SHED
	Listable	<input checked="" type="radio"/> Y <input type="radio"/> N <input type="radio"/>		
E	Building Type	CATTLE SHED		
	Date	1)	2)	3) C19
	Designer(s)			
	Materials	BR <input checked="" type="radio"/> ST <input type="radio"/> EBR <input type="radio"/> CO <input type="radio"/> IR <input type="radio"/> ME <input checked="" type="radio"/> WD		
		TI <input checked="" type="radio"/> SL <input type="radio"/> CTI <input type="radio"/> CER <input type="radio"/> AS <input type="radio"/> OTH		
	S Features/ Tech Merit			
	Date Inspected	17	10	95

---

F Site Notes/List or Scheduling Description

Cattle shed. C19. Coursed rubble sandstone. Pitched slate roof. Single storey. Gable end onto canal. Front elevation has two wide wooden-framed openings.

---

G Defects

Repairs

---



MB149 10/29