

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

A BW Region M + SW PRN 177

Waterway M + BC OS Sheet

BW Struc No NGR

Side TOW OFF CEN OTH Photo Neg No 12/34-35

BW Owned Y UK N MMS/PMS -

B County GWENT Alt Address

LA District ~~Monmouth~~ Torfaen

Parish

Address LENGTHMAN'S COTTAGE, GOUTRE WHARF

C Date Listed SAM No

Grade I II* II Protected Area NP AONB CA SSSI

Serial No Structures in Item

D Design Integ A B C D Context VIL URB ISO GRO

Setting A B C D Condition A B C D

Group Value Y N

Listable Y N Present Use STORAGE / DERELICT

E Building Type LENGTHMAN'S COTTAGE

Date 1) 2) 3) LC19

Designer(s)

Materials BR ST EBR CO IR ME WD

TI SL CTI CER AS OTH

S Features/
Tech Merit

Date Inspected 18 10 95

F Site Notes/List or Scheduling Description

Lengthman's cottage. M-LC19. Coursed rubble sandstone. Pitched slate roofs with stone and brick gable chimneys to earlier section of cottage. Two storeys. Rectangular plan, elonged by later extension in same style. Single storey outshut at right angles to original block with stone chimney and corrugated iron roof. Irregularly spaced windows to both storeys. First floor windows still wooden casements with brick heads and stone sills. Ground floor windows replaced with MC20 top-opening casements. Gable end has larger brick headed entrance, now blocked, and first storey casement. Cottage now entered through outshut doorway. The house is uninhabited, and appears to be used for storage and workshop purposes.

G Defects

Repairs



MB177 12/34

