

## BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

|   |                           |   |                    |  |
|---|---------------------------|---|--------------------|--|
| A | BW Region                 | M + SW  | PRN                | 154  |
|   | Waterway                  | M + BC  | OS Sheet           |  |
|   | BW Struc No               |   | NGR                |  |
|   | Side                      | TOW <input checked="" type="radio"/> OFF <input type="radio"/> CEN <input type="radio"/> OTH  | Photo Neg No       | 10/15+16   |
|   | BW Owned                  | <input type="radio"/> Y <input type="radio"/> U/K <input checked="" type="radio"/> N  | MMS/PMS            | <input type="radio"/>  |
| B | County                    | GWENT   | Alt Address        |  |
|   | LA District               | Monmouth  |                    |  |
|   | Parish                    |   |                    |  |
|   | Address                   | "TWYN-GLÂS", ADJACENT BR 88 (OFFSIDE)   |                    |  |
| C | Date Listed               |   | SAM No             |  |
|   | Grade                     | I <input type="radio"/> II* <input type="radio"/> II <input type="radio"/>  | Protected Area     | <input checked="" type="radio"/> NP <input type="radio"/> AONB <input type="radio"/> CA <input type="radio"/> SSSI |
|   | Serial No                 |   | Structures in Item |  |
| D | Design Integ              | A <input type="radio"/> <input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D  | Context            | VIL <input type="radio"/> URB <input checked="" type="radio"/> ISO <input checked="" type="radio"/> GRO            |
|   | Setting                   | A <input type="radio"/> <input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D  | Condition          | <input checked="" type="radio"/> A <input type="radio"/> B <input type="radio"/> C <input type="radio"/> D         |
|   | Group Value               | Y <input type="radio"/> <input checked="" type="radio"/> N  | Present Use        | HOUSE  |
|   | Listable                  | Y <input type="radio"/> <input checked="" type="radio"/> N  |                    |  |
| E | Building Type             | FARM HOUSE  |                    |  |
|   | Date                      | 1)  | 2)                 | 3) M (20<br>(EARLIER ORIGINS ?)  |
|   | Designer(s)               |   |                    |  |
|   | Materials                 | <input checked="" type="radio"/> BR <input checked="" type="radio"/> ST <input type="radio"/> EBR <input type="radio"/> CO <input type="radio"/> IR <input checked="" type="radio"/> ME <input checked="" type="radio"/> WD |                    |  |
|   |                           | <input checked="" type="radio"/> TI <input checked="" type="radio"/> SL <input type="radio"/> CTI <input type="radio"/> CER <input type="radio"/> AS <input type="radio"/> OTH  |                    |  |
|   | S Features/<br>Tech Merit |   |                    |  |
|   | Date Inspected            | 17  | 10                 | 95   |

---

F Site Notes/List or Scheduling Description

Farmhouse. MC20, possibly earlier origins. Coursed rubble stone, partly rendered and painted white. Tiled pitched roofs with gable ridge chimneys. Two storeys. L-shaped plan. Gable end onto canal, with single storey lean-to. Main block; central entrance with two modern casement windows to each floor. Wing facing canal has a random casement to each storey.

---

G Defects

Repairs

---



MB154

10/15

